

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRRES20131165, Building Permit - Residential

Address: 602 NW REDBUD DR, Unit:B, LEES SUMMIT, MO 64081602 NW REDBUD DR, Unit:C, LEES SUMMIT, MO 64081602 NW REDBUD DR, Unit:A, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	John Borns	Failed	Friday, September 26, 2014

Corrective Action Required

1 Misc 1

SECURE PEX TUBING TERMINATIONS AGAINST TORQUE WHEREVER CENTER OF VALVE IS >3" FROM PENETRATION THROUGH CABINET BASE OR BACK.

Corrective Action Required

2 Misc 1

APPARENT HOT-NEUTRAL REVERSE AT DISPOSAL RECEPTACLE AT UNIT "C"

Corrective Action Required

3 Misc 1

UNIT B: INTERNAL BEND DIAMETER OF GAS CONNECTOR UNDER FIREPLACE IS SMALLER THAN MINIMUM 1-1/2" ALLOWED BY MANUFACTURER (SEE YELLOW TAG THEREON). **REPLACE -- DO NOT RE-BEND**

Comments: