

Certificate of Occupancy

Permit #: PRCOM20140913
Address: 110 NE SAINT LUKES BLVD, Unit:245, LEES SUMMIT, MO 64086
Inspected On: Monday, September 29, 2014
Inspected By: John Borns

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - John Borns Codes Commercial	Full C of O		Monday, September 29, 2014

Comments: APPROVAL NOTIFICATION RECEIVED FROM LSFD.