

Temporary Certificate of Occupancy

Permit #: PRRES20131165
Address: 602 NW REDBUD DR, Unit:B, LEES SUMMIT, MO 64081602 NW REDBUD DR, Unit:C, LEES SUMMIT, MO 64081602 NW REDBUD DR, Unit:A, LEES SUMMIT, MO 64081
Inspected On: Tuesday, September 30, 2014
Inspected By: John Borns
Expiration Date: 10/9/2014 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	John Borns	Temporary C of O	Tuesday, September 30, 2014

Partial Correction:

1	Misc 1	EXTERIOR AND FINISH SITEWORK SUBJECT TO APPROVAL WHEN COMPLETED.
---	--------	--

Corrective Action Required:

2	Misc 1	CRAWL SPACES YET TO BE INSPECTED
---	--------	----------------------------------

UNITS A, B, & C OK FOR TEMPORARY OCCUPANCY THROUGH ABOVE DATE.