

# Certificate of Occupancy

---

**Permit #:** PRCOM20150189  
**Address:** 1211 NE RICE RD, LEES SUMMIT, MO 64086  
**Inspected On:** Monday, March 09, 2015  
**Inspected By:** Khanh Nguyen

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
<b>Occupancy Inspection - Codes Commercial</b>	Khanh Nguyen	Passed	Monday, March 09, 2015
<b>Above Ceiling Inspection</b>	Khanh Nguyen	Passed	Monday, March 09, 2015

**Comments:**  
MOBILE Z REPAIR TENANT