

Certificate of Occupancy

Permit #: PRRES20131165
Address: 600 NW REDBUD DR, Unit:B, LEES SUMMIT, MO 64081600 NW
REDBUD DR, Unit:A, LEES SUMMIT, MO 64081
Inspected On: Friday, May 01, 2015
Inspected By: John Borns

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - John Borns Codes Residential	Full C of O		Friday, May 01, 2015

Comments: VEGETATION ESTABLISHED. NO REMAINING ISSUES.