

Inspection Summary

Permit #: PRCOM20141077, Building Permit - Commercial

Address: 3341 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Mark Harding	Partial	Monday, July 20, 2015

Corrective Action Required

1	Misc 1	1ST LAYER INSIDE ELEVATOR
---	--------	---------------------------

ELEVATOR CEILING-1ST,
SOUTH TOWER 1ST LAYER
NORTH TOWER 1-2 1ST LAYER

Comments: