

Certificate of Occupancy

Permit #: PRCOM20150471
Address: 410D SE 3RD ST, Unit:102A, LEES SUMMIT, MO 64063
Inspected On: Tuesday, July 21, 2015
Inspected By: John Borns

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - John Borns Codes Commercial	Full C of O		Tuesday, July 21, 2015

Comments: RECOMMEND PRECAUTION BE TAKEN TO PREVENT INJURY AT CLEAR FLOOR-TO-CEILING SIDELIGHT AT WAITING ROOM NORTHWEST.