## PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #: PRCOM20151707, Building Permit - Commercial Address: 1160 NE DOUGLAS ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Gas Piping Inspection - Commercial	John Borns	Partial	Tuesday, August 04, 2015
Corrective Action Require 1 Misc 1	ed		G EXPOSED TO WEATHER MUST BE WITH PAINT OR BY OTHER APPROVED MEANS. ND ROOFTOP.
Gas Service Inspection - Commercial	John Borns	Partial	Tuesday, August 04, 2015
Partial Correction			
1 Misc 1		GAS PIPING PRESSURE TEST HELD STEADY AT >= 10 PSI FOR >=10 MIN ON PIPING FOR UNITS: 1194 (UNIT VACANT) 1192 - 2 (THAI SPICE) 1190 (SPRING NAILS) 1188 (UNIT VACANT) 1186 (NATURAL WAY CHIROPRACTIC) 1184 - 2 (UNIT VACANT) 1178 - 2 (CLOTHES MENTOR) 1174 - 2 (ARC PHYSICAL THERAPY) 1170 - 3 (PLATO'S CLOSET) 1166 (LASER LIKE LIPO) 1164 (SSB SALON) 1160 (UNIT VACANT)	
Corrective Action Require 2 Misc 1	ed	ADDRESS LABELING OF GAS S FROM LOAD SIDE ENTRY PIPE	SERVICE ENTRY PIPE: HANG PERMANENT TAG

Gas Service Inspection - John Borns

Partial

Tuesday, August 04, 2015

## Commercial

Partial Co	orrection	
1	Misc 1	GAS PIPING PRESSURE TEST HELD STEADY AT >= 10 PSI FOR >=10 MIN ON
		PIPING FOR UNITS:
		1194 (UNIT VACANT)
		1192 - 2 (THAI SPICE)
		1190 (SPRING NAILS)
		1188 (UNIT VACANT)
		1186 (NATURAL WAY CHIROPRACTIC)
		1184*/1182 (UNIT VACANT)
		1178 - 2 (CLOTHES MENTOR)
		1174 - 2 (ARC PHYSICAL THERAPY)
		1170 - 3 (PLATO'S CLOSET)
Correctiv	e Action Required	
2	Misc 1	ADDRESS LABELING OF GAS SERVICE ENTRY PIPE: HANG PERMANENT TAG
		FROM LOAD SIDE ENTRY PIPE.

Comments: