

Inspection Summary

Permit #: PRCOM20141074, Building Permit - Commercial

Address: 3311 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Mike Copeland	Partial	Tuesday, August 18, 2015

Partial Correction

1	FIRST FLOOR	2ND LAYER CORRIDOR LID APPROVED UNITS 1ST LAYER APPROVED
---	-------------	---

Partial Correction

2	SECOND FLOOR	2ND LAYER CORRIDOR LID APPROVED 2 HOUR CONDITIONS APPROVED
---	--------------	---

Partial Correction

3	THIRD FLOOR	2ND LAYER CORRIDOR LID APPROVED
---	-------------	---------------------------------

Partial Correction

4	LOWER LEVEL	UNITS FIRST LAYER APPROVED 2 HOUR CONDITIONS APPROVED 2ND LAYER ELEVATOR ROOM APPROVED 3RD AND FOURTH LAYER ELEVATOR ROOM FAILED DUE TO DUCT ELEVATION. STRUCTURAL BEAM STILL NEEDS PROTECTED.>>>1ST LAYER APPROVED.
---	-------------	---

Partial Correction

5	FOURTH FLOOR	ELEVATOR LID 4TH LAYER APPROVED.
---	--------------	----------------------------------

1ST LAYER CORRIDOOR APPROVED

1ST LAYER ROOM LIDS APPROVED EXCEPT 4404 AND 4408.

Partial Correction

6	Misc 1	STAIR TOWERS: 1ST LAYER APPROVED THROUGHOUT WALLS AND LIDS
---	--------	--

Comments:

