

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141074, Building Permit - Commercial
Address: 3311 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|--------------------------------------|---------------|----------|----------------------------|
| Rated Assembly Inspection | Mike Copeland | Partial | Wednesday, August 19, 2015 |

Partial Correction

| | | |
|---|-------------|---|
| 1 | FIRST FLOOR | 2ND LAYER CORRIDOR LID APPROVED UNITS 1ST LAYER APPROVED |
|---|-------------|---|

Partial Correction

| | | |
|---|--------------|---|
| 2 | SECOND FLOOR | 2ND LAYER CORRIDOR LID APPROVED 2 HOUR CONDITIONS APPROVED |
|---|--------------|---|

Partial Correction

| | | |
|---|-------------|---------------------------------|
| 3 | THIRD FLOOR | 2ND LAYER CORRIDOR LID APPROVED |
|---|-------------|---------------------------------|

Partial Correction

| | | |
|---|-------------|---|
| 4 | LOWER LEVEL | UNITS FIRST LAYER APPROVED 2 HOUR CONDITIONS APPROVED 2ND LAYER ELEVATOR ROOM APPROVED 3RD AND FOURTH LAYER ELEVATOR ROOM FAILED DUE TO DUCT ELEVATION. STRUCTURAL BEAM STILL NEEDS PROTECTED.>>>1ST LAYER APPROVED. |
|---|-------------|---|

Partial Correction

| | | |
|---|--------------|--|
| 5 | FOURTH FLOOR | ELEVATOR LID 4TH LAYER APPROVED. 1ST AND 2ND LAYER CORRIDOOR APPROVED 1ST AND 2ND LAYER ROOM LIDS APPROVED 1ST LAYER WALLS APPROVED. INSTALL BATH FANS NORTH UNITS |
|---|--------------|--|

Partial Correction

| | | |
|---|--------|--|
| 6 | Misc 1 | STAIR TOWERS: 1ST LAYER APPROVED THROUGHOUT WALLS AND LIDS |
|---|--------|--|

Comments: