PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20151156, Building Permit - Commercial Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

In-wall Inspection	John Borns	Partial	Friday, August 21, 2015
Partial Correction 1 Misc 1		SYSTEMS AT FOLLOWIN THRU (5) EAST WALL; C CORRIDORS 5A081A & PATIENT ROOMS 5A002 083; 084; 085; 086; 087 OK TO COVER SHOWER 021-030;	EADY LIGHT-GAUGE STEEL WALL FRAMING + IN-WALL IG SPACES: 5A015A; 5A007 THRU 5A021; CORR 081 (1) ORR 102 (1) THRU (5) WEST WALL; SPACE 070A; 087; 5A102 FROM (1) TO (7.5); 2 - 006 & 023 - 027; 5A068; 069; 072; 078; 081 S; 082; ; 089; 093; 095; 097; 029; 030 ALL WALLS S AT PATIENT ROOMS: 5A010A - 5A020A; 001-009; WN THAT ALL FLOOR PENETRATIONS ARE FIRE-STOPPED;
Rated Assembly Inspection	John Borns	Partial	Friday, August 21, 2015
Partial Correction			EADY COMPONENTS OF FIRE-RATED WALLS AT
1 Misc 1		LOCATIONS: FRAMING AND SHAFT LINER BOARD ON (6.1) FROM (B) TO (C); SHAFT WALLS @ 5A095 N & 097 N; 5A095 E,S,W BOTH FACES + N WALL; 5A096 E,N,W BOTH FACES + S WALL; 5A097 E,S,W BOTH FACES + N WALL + FIRE CAULK @ SW CORNER; 076, 077, 078 INTERIOR FACE ONLY; 074 & 075 S WALL; [CORR FACE ON (B) & (C) FROM (6) TO (7); 5A001 VERTICAL SHAFT AT N WALL;	