PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20151156, Building Permit - Commercial Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly John Borns Partial Tuesday, September 01, 2015

Inspection

Partial Correction

1 Misc 1 OK TO COVER WHEN READY COMPONENTS OF FIRE-RATED

WALLS AT LOCATIONS: FRAMING AND SHAFT LINER BOARD ON (6.1) FROM (B) TO (C); SHAFT WALLS @ 5A095 N & 097 N; 5A095 E,S,W BOTH FACES + N WALL; 5A096 E,N,W BOTH FACES + S WALL; 5A097 E,S,W BOTH FACES + N WALL + FIRE CAULK @ SW CORNER; 076, 077, 078 INTERIOR FACE ONLY; 074 & 075 S WALL; CORR FACE ON (B) & (C) FROM (6) TO (7); 5A001 VERTICAL SHAFT AT N WALL; WALL @ 5A029 N & 030 S INCLUDING HARD CORNER AT INTERSECION W/ CORRIDOR WALL; CORR 5A102 NORTH

BULKHEAD AT DOUBLE DOOR;

5A086 NE AT VERTICAL MECHANICAL CHASE OK TO COVER: FRAMING + SHAFT LINER; 5/8" TYPE X GWB AT CORRIDOR RECESS ON (2.8) FROM (A.9) TO (B.1) + **5/8**" **TYPE X AT BOTH WALL**

PLANES IN 5A086;

In-wall Inspection John Borns Partial Tuesday, September 01, 2015

Partial Correction

1 Misc 1 OK TO COVER WHEN READY LIGHT-GAUGE STEEL WALL FRAMING

+ IN-WALL SYSTEMS AT FOLLOWING SPACES: 5A015A; 5A007 THRU 5A021; CORR 081 (1) THRU (5) EAST WALL; CORR 102 (1) THRU (5) WEST WALL; SPACE 070A; 087; CORRIDORS 5A081A &

5A102 FROM (1) TO (7.5);

PATIENT ROOMS 5A002 - 006 & 023 - 027; 5A068; 069; 072; 078; 081 S; 082; 083; 084; 085; 086; 087; 089; 093; 095; 097; 028; 029;

030 N WALL; **5A085 SE AT MECH SHAFT**

OK TO COVER SHOWERS AT PATIENT ROOMS: 5A010A - 5A020A; 001-009; 021-030;

PROVIDE CERTIFICATION THAT ALL FLOOR PENETRATIONS ARE FIRE-STOPPED;

Comments: