## PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #: PRCOM20141077, Building Permit - Commercial Address: 3341 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly Mark Harding Failed Wednesday, November 25,

Inspection 2015

**Corrective Action Required** 

1 Misc 1 1ST LAYER INSIDE ELEVATOR

ELEVATOR CEILING-1ST,2,3, 4 LAYERS APPROVED

SOUTH TOWER 1ST LAYER2nd NORTH TOWER 1-2nd, 3,4

- CORRIDOR CEILING 2ND LAYER 1,2,3

**TUB WALLS-**

2HR TUB WALLS 1ST, 2ND LAYERS

units 1st layer

1st floor unit side 1st layer 2nd,3,4th ceiling only

1STLAYERS STAIR TOWER CEILING1,2,3,4 AND DROP 1st,2ND,3rd ,4TH LAYER ELEVATOR EQUIPMENT ROOM

PLUMB PENS 1,2OK 3,4 NOT READY

**Partial Correction** 

2 FIRST FLOOR 1st floor garage need to enclose north garage i beam

2ND LAYER 2 HOUR CONDITIONS APPROVED

**Partial Correction** 

3 SECOND FLOOR 2ND LAYER 2 HOUR CONDITIONS APPROVED

**Partial Correction** 

4 THIRD FLOOR 1ST LAYER WALLS AND CEILING APPROVED

2hr walls-

unit bathrooms 6304,6305,6306 nail patterN

2ND LAYER WALLS @ 2 HR CONDITIONS - 3RD FLOOR; 1ST LAYER

CORRIDORS STAIR TOWERS AT SIDE ENTRY;

**Partial Correction** 

5 FOURTH FLOOR 1ST LAYER WALLS AND CEILING APPROVED

2ND LAYER

2ND LAYERS 2HR WALLS

## **Comments:**