

# Certificate of Occupancy

---

**Permit #:** PRCOM20152661  
**Address:** 319 SE DOUGLAS ST, Unit:313, LEES SUMMIT, MO 64063  
**Inspected On:** Thursday, December 17, 2015  
**Inspected By:** John Borns

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	John Borns	Full C of O	Thursday, December 17, 2015

**Comments:**