

Inspection Summary

Permit #: PRRES20152714, Building Permit - Residential

Address: 249 SE COYLE DR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Driveway Inspection	Bob Burns	Partial	Tuesday, March 22, 2016

Comments: