

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #: PRRES20150531, Building Permit - Residential

Address: 3353 SW JESSIE LN, LEES SUMMIT, MO 64082			
This work has been inspect once all corrective actions h	•		•
Inspection:	Inspector:	Outcome:	Date:
PW-ADA Inspection	Brice Lawson	Passed	Wednesday, March 23, 2016
Informational  1 The forms are set	and the rock has been c	ompacted.	
PW-Sidewalk Inspection	Brice Lawson	Passed	Wednesday, March 23, 2016
Corrective Action Required  1 An ADA panel is r	equired for your sidewall	k crossing.	
The plot plan sho install an ADA rar Informational		he curb. The curb will need	d to be removed to
	ns are set and the rock h	as been compacted.	
Comments:			