

Inspection Summary

Permit #: PRCOM20160190, Building Permit - Commercial
Address: 1100 NE DOUGLAS ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Hood/Duct Inspection	John Borns	Partial	Wednesday, April 27, 2016

Partial Correction
1 Misc 1

**GREASE DUCT LIGHT TEST:
VERTICAL STRAIGHT SECTION: OK TO INSTALL AFTER ONE HOLE
AT JOINT CORNER IS WELDED;**

Gas Piping Inspection - Commercial	John Borns	Passed	Wednesday, April 27, 2016
---	------------	--------	---------------------------

Comments: PRESSURE TEST HELD STEADY ON NEW GAS PIPING AT KITCHEN.