

## Inspection Summary

Permit #: PRRES20152451, Building Permit - Residential  
Address: 417 SE MILL CREEK CIR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Mike Copeland	Failed	Wednesday, May 04, 2016

### Corrective Action Required

1	Misc 1	-NAIL SIDING PER MANUFACTURER. RE NAIL ANY NAILS OVERDRIVEN 1/8TH INCH. -FIREBLOCK AND FIRESTOP THROUGHOUT -ANCHOR GARAGE COLUMN WITH APPROVED ANCHOR -BLOCK POINT LOAD NEXT TO STAIRS IN BASEMENT -FUR DOWN BASEMENT FOR GYP BOARD -SHIM ALL CRIPPLE STUDS FOR FULL HEADER BEARING -INSTALL ADDITIONAL JOIST IN REAR BASEMENT WHERE JOIST SPACED 24" -REPAIR BRACED WALL MASTER BED -BLOCK KITCHEN ISLAND 48" O.C. PER PLANS -SPLICES IN GARAGE PORTAL SHEATHING TO BE WITHIN 24" MID HEIGHT -SOLID BLOCK FIREPLACE CANTILEVER  DO NOT INSULATE
---	--------	--

<b>Gas Service Inspection - Residential</b>	Mike Copeland	Passed	Wednesday, May 04, 2016
---	---------------	--------	-------------------------

<b>Electrical Service Inspection - Residential</b>	Mike Copeland	Passed	Wednesday, May 04, 2016
--	---------------	--------	-------------------------

**Gas Piping Inspection - Mike Copeland**    Passed  
**Residential**

Wednesday, May 04, 2016

**Comments:**