

Inspection Summary

Permit #: PRRES20152404, Building Permit - Residential

Address: 3337 SW JESSIE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Mike Copeland		Failed	Monday, May 23, 2016
Codes Residential			

Corrective Action Required

1	Misc 1	-OPEN GROUND GARAGE EAST WALL RECEPTACLE -FIRE CAULK HOSE BIBB IN GARAGE -INSTALL SELF CLOSING DEVICE GARAGE DOOR TO HOUSE -INCOMPLETE DECK GAURDS AND STAIRS -LABEL ELECTRIC PANEL -TWO RECEPTACLES IN UNFINISHED BASEMENT AND 3 IN GARAGE NOT GFCI PROTECTED -TWO OPEN BOXES UNFINISHED BASEMENT CEILING -INSTALL FINAL GRADE, SOD, SPLASHBLOCKS -RESTORE VEGETATION IN DISTURBED AREAS ON ADJOINING LOTS
---	--------	---

Comments: