

**PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201**

Inspection Summary

Permit #:PRRES20152714, Building Permit - Residential
Address: 249 SE COYLE DR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Electrical Service Inspection - Residential	Mike Copeland	Not Ready	Friday, June 03, 2016

Corrective Action Required

1	Misc 1	DENIED DUE TO LACK OF EROSION CONTROL NORTH PROPERTY AND DAMAGE TO ADJOING PROPERTY
---	--------	---

All Rough Inspection - Residential	Mike Copeland	Not Ready	Friday, June 03, 2016
---	---------------	-----------	-----------------------

Corrective Action Required

1	Misc 1	NO INTERIOR VIOLATIONS, OKAY TO INSULATE AND ROCK. CEDAR POSTS FOR COVERED DECK ARE EMBEDDED IN CONCRETE. THIS NEEDS TO BE RESOLVED BEFORE FINAL.
---	--------	--

Gas Service Inspection - Residential	Mike Copeland	Not Ready	Friday, June 03, 2016
---	---------------	-----------	-----------------------

Corrective Action Required

1	Misc 1	DENIED DUE TO LACK OF EROSION CONTROL NORTH PROPERTY AND DAMAGE TO ADJOING PROPERTY
---	--------	---

Comments: