

Certificate of Occupancy

Permit #: PRCOM20152703
Address: 123 SE 3RD ST, LEES SUMMIT, MO 64063
Inspected On: Tuesday, July 05, 2016
Inspected By: John BornsRon SeylRon Seyl

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	John Borns	Full C of O	Tuesday, July 05, 2016
Occupancy Inspection - Planning	Ron Seyl	Passed	Tuesday, July 05, 2016

Comments: