

Certificate of Occupancy

Permit #: PRRES20152404
Address: 3337 SW JESSIE CIR, LEES SUMMIT, MO 64082
Inspected On: Friday, July 08, 2016
Inspected By: Mike Copeland

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Mike Copeland Codes Residential	Full C of O		Friday, July 08, 2016

Comments: