

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20160711, Building Permit - Residential
Address: 258 SE COYLE DR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Friday, July 29, 2016

Corrective Action Required

1	Misc 1	-FIREBLOCK GARAGE CHASE **FB GAPS. ALSO FB FIREPLACE SPACE AND BASEMENT PER CODE -THE SHORT SILL PLATE AT SW CORNER REQUIRED TO HAVE MINIMUM 2 ANCHOR BOLTS -OVER BED 3 SE BASEMENT BED, HANGER FOR FJ 14 AND DOUBLE LVL. **FIELD-MODIFIED HANGER? HAVE ENGINEER OK THAT OR INSTALL A PROPER ONE -OVER FURNACE AND INSTALL HANGERS PER LAYOUT. **INSTALL WEB FILLER AT DOUBLE TJI CONNECTION. THE HANGER INSTALLATION FOR THE REMAINING JOISTS IS WRONG. GET PROPER SIZE HANGERS FOR THE JOIST CONNECTIONS **OK TO INSULATE
---	--------	--

Comments: