

Certificate of Occupancy

Permit #: PRCOM20161193
Address: 1196 NE DOUGLAS ST, LEES SUMMIT, MO 64086
Inspected On: Friday, August 19, 2016
Inspected By: John BornsJohn Borns

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	John Borns	Full C of O	Friday, August 19, 2016
Above Ceiling Inspection	John Borns	Passed	Friday, August 19, 2016

Comments: