

## **CODES ADMINISTRATION**

## **Certificate of Occupancy**

| Permit #: | PRRES20150529 |
|-----------|---------------|
|           |               |

Address: 3328 SW JESSIE LN, LEES SUMMIT, MO 64082

Inspected On: Monday, August 29, 2016

Inspected By: Mike Copeland

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.** 

Inspection: Outcome: Date:

Occupancy Inspection - Mike Copeland Full C of O Monday, August

Codes Residential 29, 2016

**Comments:**