

# Certificate of Occupancy

---

**Permit #:** PRCOM20160500  
**Address:** 110 NE SAINT LUKES BLVD, Unit:300, LEES SUMMIT, MO 64086  
**Inspected On:** Thursday, September 15, 2016  
**Inspected By:** John Borns

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
<b>Occupancy Inspection -</b> John Borns	Full C of O		Thursday, September 15, 2016
<b>Codes Commercial</b>			

**Comments:**