

# Certificate of Occupancy

---

**Permit #:** PRCOM20162031  
**Address:** 107 SE M 291 HWY, LEES SUMMIT, MO 64063  
**Inspected On:** Wednesday, September 21, 2016  
**Inspected By:** Mike Copeland

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
<b>Occupancy Inspection</b> - Mike Copeland <b>Codes Commercial</b>	Full C of O		Wednesday, September 21, 2016

**Comments:**