

PLANNING AND CODES ADMINISTRATION DEPARTMENT  
220 SE GREEN STREET  
LEE'S SUMMIT, MO 64063  
(816) 969-1200 FAX (816) 969-1201

## Inspection Summary

---

Permit #:PRCOM20161080, Building Permit - Commercial  
Address: 521 SE 2ND ST, Unit:B, LEES SUMMIT, MO 64063

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Above Ceiling Inspection</b>	John Borns	Partial	Thursday, October 06, 2016

Partial Correction  
1 Misc 1

CONTRARY TO EARLIER DIRECTION AND AGREEMENT BORDER  
TILES HAVE BEEN PLACED BEFORE ABOVE-CEILING INSPECTION.  
CLOSE ALL ELECTRICAL JUNCTION BOXES BEFORE PLACING  
CEILING TILE. **DO NOT PLACE CEILING TILE AT RESTROOM OR AT  
MED GAS CLOSET.**

Corrective Action Required  
2 Misc 1

**MED GAS VENT MAY NOT BE EXHAUSTED THROUGH PLASTIC  
VENT TUBE -- AS DISCUSSED EARLIER, USE SHEET METAL DUCT.**

**Comments:**