

Temporary Certificate of Occupancy

Permit #: PRRES20160937
Address: 400 SE MILL CREEK DR, LEES SUMMIT, MO 64063
Inspected On: Tuesday, November 15, 2016
Inspected By: Mike CopelandMike Copeland
Expiration Date: 12/8/2016 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Mike Copeland	Temporary C of O	Tuesday, November 15, 2016

Corrective Action Required:

1 Misc 1
- deck header around boxout needs to be doubled.

Occupancy Inspection - Codes Residential	Mike Copeland	Failed	Tuesday, November 15, 2016
---	---------------	--------	-------------------------------

Corrective Action Required:

1 Misc 1
flue clearance to combustible bsmt ceiling
- deck header around boxout needs to be doubled.