S LEE'S SUMMIT M | S S O U R I

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20163086, Public Works Infrastructure Permit - Commercial SAINT LUKE'S EAST - WEST PARKING LOT Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item: Inspection:		Inspector:	Outcome:	Date:
			outcome:	Date
PW-Storm - Sewer		Steve Robbins	Partial	Thursday,
Construction Inspection				December 22, 2016
Informational				
1	No work was done today due to the cold and snow.Steve Robbins 12/19/2016 3:52 PM			
Informational				
2	Today they installed aproximately 55 ft. of 60" concrete stormpipe and put in rock. Steve			
	Robbins 12/14/2016	3:40 PM		
Informational				
3	No work was done today due to the cold weather and snow.Steve Robbins 12/19/2016			
	3:48 PM			
Informational				
4	Structure 109 and 108 have been installed and the collars have been poured or			
	Today they installed structure 107 and 106 and the pipe with rock, tomorrow they are			
		the collars for those structι	•••	•
Informational				
5	So far today they ha	ve installed structure 105 and	d 104, they are planning on	pouring the
	collars for the last 4	structures this afternoon afte	er lunch. They have the pipe	and rock for
		Robbins 12/21/2016 12:06 PN		
Informational				

6 They put storm pipe from structure 104 to 103, Steve Robbins 12/22/2016 4:26 PM

Comments: