PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20162583, Building Permit - Commercial Address: 20 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Above Ceiling John Borns Partial Wednesday, December 28,

Inspection 2016

Partial Correction

1 Misc 1 OK TO COVER WHEN READY ACT CEILING FRAMING +

ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: 1C216; 1C133
AFTER HANGING CONDUIT IS SECURED OR REMOVED, FLEX
PENETRATION OF RATED WALL IS FIRE-STOPPED, AND COPPER
PIPE IS ISOLATED FROM STEEL TOP TRACK; C137 AFTER HVAC
DIFFUSER IS IN PLACE AND FLEX DUCT HAS PROPER LENGTH

WITH NO KINKS;

In-wall Inspection John Borns Partial Wednesday, December 28,

2016

Partial Correction

1 Misc 1 OK TO COVER WHEN READY LIGHT-GAUGE STEEL WALL FRAMING

+ IN-WALL SYSTEMS AT FOLLOWING LOCATIONS: 1C122 SOUTH WALL; 1C216; 1C217; CUT-IN DOOR 1C219; 1D23 NW WALL B/F; 1D25; 1D26; IN-FILL AT 1D22 N WALL B/F; 1D24 B/F; 1D25 O/SF;

1D26 W WALL B/F; 1D221 E WALL B/F; 1C223; 1C221

CONTINGENT ON SEGMENT OF CORRIDOR SMOKE WALL BEING SMOKE-SEALED; C137; E/NE WALL; 1C120 & 121 B/F; 1C218 E & S

WALLS;

B/F = BOTH FACES O/SF = OUTSIDE FACE

Comments: