

---

**PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

---

Permit #: PRPWFC20162083, Public Works Infrastructure Permit - Commercial

WATER UTILITIES FACILITY

Address: 1200 SE HAMBLER RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection Item:

<b>Inspection:</b>	<b>Inspector:</b>	<b>Outcome:</b>	<b>Date:</b>
PW-Sanitary Sewer - Air Test	Brice Lawson	Partial	Wednesday, January 04, 2017

Informational

- 1 Brice Lawson 01/04/2017 4:03 PM  
She Digs It pressure tested the 8" sanitary line between MH-A1 and MH-A2 and the 8" sanitary line between MH-A2 and MH-A3. Both of these tests passed.

**Comments:**

---