

Certificate of Occupancy

Permit #: PRCOM20163284
Address: 319 SE DOUGLAS ST, Unit:317, LEES SUMMIT, MO 64063
Inspected On: Friday, January 13, 2017
Inspected By: John Borns

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - John Borns	Full C of O		Friday, January 13, 2017
Codes Commercial			

Comments: