PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20152438, Building Permit - Commercial Address: 3381 NW CHIPMAN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Above Ceiling John Borns Partial Monday, January 23, 2017

Inspection

Partial Correction

2 Misc 1 OK TO COVER WHEN READY ACT CEILING FRAMING +

ABOVE-CEILING SYSTEMS @: 130; 131; 133; 134; 136; 138; 141;

143; 145; 147; 149; 152; 153;

Rough Framing John Borns Partial Monday, January 23, 2017

Inspection -Commercial

Partial Correction

1 Misc 1 OK TO COVER WHEN READY L.G. STEEL FURRING FRAMING PER

WALL SECTION 1/E1 ON ERECTION DRWG. TAPCON FASTENING

APPROVED PER DETAIL 4/S4.01.

Partial Correction

2 Misc 1 OK TO COVER WHEN READY FRAMING ONLY AT: SOUTH WALL OF

120 OK FOR CONSTRUCTION OF ADJACENT RAMP; RAISED FLOOR FRAMING AT 121-127; SAME AT 120; FRAMING OF PLATFORM AT

[128]; 7" HIGH PLATFORMS @ 137 & 140

In-wall Inspection John Borns Partial Monday, January 23, 2017

Partial Correction

1 Misc 1 OK TO COVER WHEN READY LIGHT-GAUGE STEEL WALL FRAMING

+ IN-WALL SYSTEMS AT FOLLOWING LOCATIONS:

ONE-SIDING OF ELECT[115]; VEST [118] N WALL TWO LAYERS S FACE; TWO 4' WIDE STACKS @ PLATFORM [117] FOR DUCTWORK;

MECH [145]; WOMENS RR [103]; MEN'S RR[104]; JANITOR [105]; FAMILY RR [106]; ELECT [115] SOUTH WALL SOUTH FACE; 102; 129; 144; 114 NORTH WALL; [116] S/SW WALLS; PLATFORM [117] EAST, SOUTH & NORTH WALLS;

SOUTH WALL OF E-W LEG OF N END OF CORR [128]; [131]-[143]; [145]; [147]-[150]; [157]; [151] THROUGH [156];

IN-WALL OK FOR: SANCTUARY 113 STARTING FROM PLATFORM (117) STAIR ALL THE WAY AROUND TO THE OTHER SIDE; RM 107 TO 112; DOUBLE STUD WALL BETWEEN 113&102; **CORRIDOR** [128]

Comments: