

**PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201**

Inspection Summary

Permit #:PRCOM20162583, Building Permit - Commercial
Address: 20 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
In-wall Inspection	John Borns	Partial	Wednesday, January 25, 2017

Partial Correction
1 Misc 1

OK TO COVER WHEN READY LIGHT-GAUGE STEEL WALL FRAMING + IN-WALL SYSTEMS AT FOLLOWING LOCATIONS: 1C122 SOUTH WALL; 1C216; 1C217; CUT-IN DOOR 1C219; 1D23 NW WALL B/F; 1D25; 1D26; IN-FILL AT 1D22 N WALL B/F; 1D24 B/F; 1D25 O/SF; 1D26 W WALL B/F; 1D221 E WALL B/F; 1C223; 1C221
CONTINGENT ON SEGMENT OF CORRIDOR SMOKE WALL BEING SMOKE-SEALED; C137; E/NE WALL; 1C120 & 121 B/F; 1C218 E & S WALLS; [1C118] E & NW; [1C120] S WALL; [1C218] N WALL AFTER 2 BOCA PLATES IN PLACE; WALL AT/ADJACENT TO DOOR (1D23); [1C118] W WALL; [1C118A] E WALL; [1C119] S WALL; CHASE AT [218] SE CORNER; [1C219] E & W WALLS; WING WALL @ [1C219] S; N WALL OF NEWLY-ENCLOSED CLOSET PER PR#5 AT [1D23] SOUTH; **[1C211] N WALL B/F; FRAMING AT DOOR OPENINGS (1C101) & (1C197) B/F;**

B/F = BOTH FACES
O/SF = OUTSIDE FACE

Comments: