## PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #:PRCOM20162583, Building Permit - Commercial Address: 20 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

In-wall Inspection John Borns Partial Wednesday, February 01, 2017

**Partial Correction** 

1 Misc 1

OK TO COVER WHEN READY LIGHT-GAUGE STEEL WALL FRAMING + IN-WALL SYSTEMS AT FOLLOWING LOCATIONS: 1C122 SOUTH WALL; 1C216; 1C217; CUT-IN DOOR 1C219; 1D23 NW WALL B/F; 1D25; 1D26; IN-FILL AT 1D22 N WALL B/F; 1D24 B/F; 1D25 O/SF; 1D26 W WALL B/F; 1D221 E WALL B/F; 1C223; 1C221 CONTINGENT ON SEGMENT OF CORRIDOR SMOKE WALL BEING SMOKE-SEALED; C137; E/NE WALL; 1C120 & 121 B/F; 1C218 E & S WALLS; [1C118] E & NW; [1C120] S WALL; [1C218] N WALL AFTER 2 BOCA PLATES IN PLACE; WALL AT/ADJACENT TO DOOR (1D23); [1C118] W WALL; [1C118A] E WALL; [1C119] S WALL; CHASE AT [218] SE CORNER; [1C219] E & W WALLS; WING WALL @ [1C219] S; N WALL OF NEWLY-ENCLOSED CLOSET PER PR#5 AT [1D23] SOUTH; [1C211] N WALL B/F; FRAMING AT DOOR OPENINGS (1C101) & (1C197) B/F; [1C101];

B/F = BOTH FACES O/SF = OUTSIDE FACE

Above Ceiling Inspection

John Borns

**Partial** 

Wednesday, February 01, 2017

**Partial Correction** 

1 Misc 1 OK TO COVER WHEN READY ACT CEILING FRAMING +

ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: 1C216; 1C133; C137; [1D25]; 1C217; 1C218A; 1C219; 1C221; 1C223; **1C218** 

**INCLUDING EAST 1/2; 1D24;** 

**Comments:**