

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

Permit #: PRPWFC20163086, Public Works Infrastructure Permit - Commercial  
SAINT LUKE'S EAST - WEST PARKING LOT  
Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

**Inspection Item:**

<b>Inspection:</b>	<b>Inspector:</b>	<b>Outcome:</b>	<b>Date:</b>
PW-ESC - (Vegetation/Ground Cover) Informational	Steve Robbins	Partial	Friday, March 03, 2017
1	The straw matting was finished being installed today around the detention basin. They still need to put some coming down the sides. Steve Robbins 03/03/2017 2:33 PM		
Informational			
1	Today they started to install the seed and straw rolls on the hill of the detention basin that has been installed. They are on the west side of th detention basin. Steve Robbins 03/02/2017 10:41 AM		

**Comments:**