

**PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

---

Permit: PRPWFR20152896, Infrastructure Permit - Residential

Trails of Park Ridge and Trails of Park Ridge Access Road, Trails of Park Ridge, Lee's Summit

---

Site has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed.

---

<b>Inspection:</b>	<b>Inspector:</b>	<b>Outcome:</b>	<b>Date:</b>
Erosion Sediment Control (ESC) Inspection	Barton Reese	Action Required	April 06, 2017

**Corrective Action Required**

ESC required on vacant land on E-W Chapel Manor Drive east of Timberlake Dr.

ESC required on vacant land on west side of Timberlake Dr. between Chapel Woods Dr. and Parkwood Dr. (Trails of Park Ridge 1st Plat)

ESC required on vacant land on south side of Parkwood Dr. at intersection of Parkwood Dr. and Timberlake Dr. (Trails of Park Ridge 1st Plat)

ESC required on vacant land on N-S Chapel Manor Dr. between Chapel Woods Dr. and Parkwood Dr. (Trails of Park Ridge 2nd Plat)

**Comments: establish erosion and sediment control devices/measures. Vegetative ground cover is the best erosion/sediment control. Photos will be sent with this insp. summary.**

---