

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20163086, Public Works Infrastructure Permit - Commercial

SAINT LUKE'S EAST - WEST PARKING LOT

Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection item:	Inspector:	Outcome:	Date:
PW-Stabilized Subgrade	Steve Robbins	Partial	Monday,

April 24, 2017

Informational

Today they continued to get the grade ready for rock and ge-grid, this is south end of the parking lot that they are merging with the existing. The subgrade is ready to have rock and geo-grid installed. Steve Robbins 04/24/2017 2:32 PM

Comments: