

STOP WORK ORDER

**ANY UNAUTHORIZED PERSON REMOVING THIS NOTICE WILL BE
PROSECUTED**

Permit #: PRRES20171327
Address: 1816 SW BLACKSTONE PL, LEES SUMMIT, MO 64082
Inspected On:
Inspected By:

Any person who shall continue work after having been served with a stop work order, except such work as that person is directed to perform to remove a violation or unsafe condition, shall be subject to penalties as prescribed by law.

Inspection: Misc Inspector: Mark Outcome: Failed Date: 5-10-2017
Harding

Comments: Subdivision storm pipe was damaged during excavation of foundation. Repair to be completed prior to lifting stop work order. Mitch Plemmons