

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #: PRPWFC20163086, Public Works Infrastructure Permit - Commercial

SAINT LUKE'S EAST - WEST PARKING LOT

Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:			
Inspection:	Inspector:	Outcome:	Date:
PW-Proof roll parking lot	Steve Robbins	Partial	Monday, May

15, 2017

## Informational

I talked to the contractor about a prooroll and they said they are getting close. They have installed all the curbs and the parking lot has been drying out. Steve Robbins 05/15/2017 10:04 AM

## **Comments:**