

Inspection Summary

Permit #: PRRES20162127, Building Permit - Residential
Address: 320 SE MILL CREEK DR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Electrical Service Inspection - Residential	Mike Copeland	Failed	Tuesday, May 23, 2017

Corrective Action Required

1	Misc	DRIVE TWO ADDITIONAL GROUND RODS DUE TO THE UNCERTAINTY OF THE INTEGRITY OF THE REBAR AND CONNECTION.
---	------	---

Comments: