## PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063

## (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #:PRCOM20161178, Building Permit - Commercial Address: 1800 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Underground Electrical John Borns Partial Tuesday, May 23, 2017

Inspection - Commercial

**Partial Correction** 

1 Misc OK TO POUR WHEN READY LIGHT POLE BASES AT FOLLOWING

LOCATIONS NUMBERED ON SITE PLAN IN PERMIT PRINT SET: #2;

4; 5; 7; 8; **9 - 13**;

**Partial Correction** 

2 Misc OK TO COVER WHEN READY TRENCHED PVC CONDUIT: FROM

L.P.#2 ONE 1" TO 80' WEST + ONE 3/4" TO 28' WEST CONN TO EXSTG; ONE 1" FROM PL#2 TO 45' NE FOR BL; ONE 1"  $\sim$ 80'

ACROSS FRONT ENTRANCE FROM BL TO BL; ONE 3/4" FROM LP#7 ~110' NW FOR BL; ONE 1" FROM PL#7 NORTH 20' TO Q-BOX

LOCATION; ONE 1" FROM Q-BOX LOCATION NW TO BL LOCATION EAST OF ENTRANCE CANOPY; GROUND ROD FOR LP#7 LAID IN

CONDUIT TRENCH DUE TO ROCK CONDITIONS;

**In-wall Inspection** John Borns Partial Tuesday, May 23, 2017

**Partial Correction** 

1 Misc OK TO COVER WHEN READY WALL FRAMING AND IN-WALL

SYSTEMS AT: 106; 107; 110; 111; 127; 128; 131; 133; 134; 135; 136; 137; 138; 143; 145; 148; 149; 154; 155; 156; 157; 159; 162; **[104; 105; 108; 109; 112; 117; 118; 119; 121; 123; 129; 132; 141;** 

142; 144; 146; 147; 158; 161; 163;

Rated Assembly John Borns Partial Tuesday, May 23, 2017 Inspection

**Partial Correction** 

1 Misc OK TO COVER WHEN READY COMPONENTS OF RATED WALL

ASSEMBLIES: PRE-ROCK ON S WALL OF SPACE 110 ONCE TAPED &

MUDDED;

**Partial Correction** 

2 Misc OK TO COVER WHEN READY COMPONENTS OF UL P522 RATED

CEILING ASSEMBLIES AT SPACES: 126; 136-138; 141- 144; 147;

148; 154-158; 159; 161; 162;

## **Comments:**