

**PLANNING AND CODES ADMINISTRATION DEPARTMENT**  
**220 SE GREEN STREET**  
**LEE'S SUMMIT, MO 64063**  
**(816) 969-1200 FAX (816) 969-1201**

## Inspection Summary

---

Permit #:PRCOM20161178, Building Permit - Commercial  
Address: 1800 NW OBRIEN RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Underground Electrical Inspection - Commercial</b>	John Borns	Partial	Wednesday, June 07, 2017

Partial Correction

1 Misc

OK TO POUR WHEN READY LIGHT POLE BASES AT FOLLOWING LOCATIONS NUMBERED ON SITE PLAN IN PERMIT PRINT SET: #2; 4; 5; 7; 8; 9 - 13; #13(REPLACEMENT OF DAMAGED BASE); #14; 15;

Partial Correction

2 Misc

OK TO COVER WHEN READY TRENCHED PVC CONDUIT: FROM L.P.#2 ONE 1" TO 80' WEST + ONE 3/4" TO 28' WEST CONN TO EXSTG; ONE 1" FROM PL#2 TO 45' NE FOR BL; ONE 1" ~80' ACROSS FRONT ENTRANCE FROM BL TO BL; ONE 3/4" FROM LP#7 ~110' NW FOR BL; ONE 1" FROM PL#7 NORTH 20' TO Q-BOX LOCATION; ONE 1" FROM Q-BOX LOCATION NW TO BL LOCATION EAST OF ENTRANCE CANOPY; GROUND ROD FOR LP#7 LAID IN CONDUIT TRENCH DUE TO ROCK CONDITIONS; FROM L.P.#10 TO #11 TO #12; #13 TO #9 TO #10; **FROM #12 TO #14 TO #15;**

**Rated Assembly Inspection**

John Borns

Partial

Wednesday, June 07, 2017

Partial Correction

1 Misc

OK TO COVER WHEN READY COMPONENTS OF RATED WALL ASSEMBLIES: 110; 142; 147; 148; 157; 158; **[106; 107; 117; 118; 127; 128; 135-138; 143; 145;**

Partial Correction

2 Misc

OK TO TAPE, MUD, & FIRE-STOP WHEN UL P522 RATED CEILING ASSEMBLIES AT SPACES: 104-108; 110; 117; 118; 121-123;

Partial Correction

3            Misc

125-129; 132; 135; 136-138; 141- 144; 147; 148; 154-158; 159;  
161; 162; [108, 113; 115;

PP1 WALLS: SHAFT LINER LAYER APPROVED; OK TO APPLY 5/8"  
TYPE X AT OPPOSITE FACE AT C113 WEST & C157 EAST;

**Comments:**