

**PLANNING AND CODES ADMINISTRATION DEPARTMENT**  
**220 SE GREEN STREET**  
**LEE'S SUMMIT, MO 64063**  
**(816) 969-1200 FAX (816) 969-1201**

## Inspection Summary

---

Permit #:PRCOM20160939, Building Permit - Commercial  
Address: 3320 NE WILSHIRE DR, LEES SUMMIT, MO 64064

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Underground Electrical Inspection - Commercial</b>	Khanh Nguyen	Partial	Friday, June 16, 2017

Partial Correction

1	Misc	UNDERGROUND ELECTRICAL OK BELOW: -UE FOR EXTERIOR LIGHTS AND POWER  LIGHT POLES PIERS: -6 LP PIERS OK TO POUR
---	------	---

<b>All Rough Inspection - Commercial</b>	Khanh Nguyen	Failed	Friday, June 16, 2017
--	--------------	--------	-----------------------

Corrective Action Required

1	Misc	ZONE A ALL-ROUGH: -FIRECAULK ALL PLUMBING PENETRATIONS OF CEILING -INSTALL FIRE DAMPERS AT ALL DUCT PENETRATION OF RATED CEILING MEMBRANE -PROTECT WIRING NEAR ATTIC ACCESS -ANCHOR SILL PLATE WITHIN 12" OF BREAKS; 2 ANCHORS PER SHORT PLATE -INSTALL STUD SHOE AT LOAD BEARING WALL WHERE BORED MORE THAN 40% -INSTALL TOP LID AT ALL DEAD SPACES. SEAL AROUND GAP -PROTECT PLUMBING WHERE WITHIN 1.5" OF NAILING SURFACE -SHEAR WALL TIE DOWN-TIGHTEN NUT IN RM 106;
---	------	--

**Comments:**