

# STOP WORK ORDER

**ANY UNAUTHORIZED PERSON REMOVING THIS NOTICE WILL BE  
PROSECUTED**

---

**Permit #:** PRRES20171896  
**Address:** 1820 SW BLACKSTONE PL, LEES SUMMIT, MO 64082  
**Inspected On:** 06-29-17  
**Inspected By:** Mitch Plemmons

---

Any person who shall continue work after having been served with a stop work order, except such work as that person is directed to perform to remove a violation or unsafe condition, shall be subject to penalties as prescribed by law.

Inspection:ECD	Inspector:Mitch Plemmons	Outcome: Failed	Date: 6-29-17
----------------	-----------------------------	--------------------	------------------

**Comments:** NO Erosion Control