PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161177, Building Permit - Commercial Address: 500 NW MOORE ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	(Outcome:	Date:
Rated Assembly Inspection	John Borns	I	Partial	Thursday, July 20, 2017
Partial Correction 2 Misc		INTERIC FRAMIN 102; 202 WEST S ^T FRAMIN FIRE-BLI (303); [4 SE STAII	2; 203; 213; 302; 303; 313; TAIRWELL: NG + SHAFT LINER BOARD OCKING WELL FACE + OF AT 4TH FLOOR (402) COM	WELL FACE + UNIT SIDE AT: 314; INCLUDING CLIPS AND PPOSITE FACE AT 3RD FLOOR
Partial Correction 3 Misc		CEILING OK TO T AND W/ CEILING 204; 20!	ALLS AT: 6 ONLY AT 201;	NT: WALLS ABOVE 4TH FLR 2 5/8" TYPE X GWB CEILINGS 212; 214; 215; CORR 216; 217;

		CORR 301/316/325; 304; 305; 306; 307; 308; 309; 310; 311; 312; 314; 315; 317; 322; 323; 324;
		4TH FLOOR CORRIDOR COMPLETE + ALL UNITS/ROOMS INCLUDING 408
Partial Co	rrection	
4	Misc	DUCT CHASE AT 303 SW CORNER: TWO LAYERS 5/8" TYOE X GWB AT CORRIDOR WALL OK TO TAPE & MUD, THEN TO INSTALL DUCT, THEN TO INSTALL PART OF SHAFT LINER ENCLOSURE, LEAVING OPENING FOR INSPECTION BEFORE COMPLETELY CLOSING CHASE.
		DUCT CHASE AT 306 SW CORNER: SIMILAR TO 303 ABOVE.

Comments: