

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #: PRPWFR20171420,	Public Works Infrastructure Permit - Residential
CREEKSIDE AT RAIN	TREE

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:
Inspection: Inspector: Outcome: Date:

PW-Erosion Sediment Control Brice Lawson Failed Tuesday, July (ESC) Inspection 25, 2017

Corrective Action Required

1 Brice Lawson 07/25/2017 2:00 PM
There are revisions to the original ESC plans.

Install the ESC devices as shown on the revised set of plans.

Repair the perimeter silt fence below temp. sediment trap #2. Add more stakes in this location.

**Comments:**