## PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

## Inspection Summary

Permit #:PRRES20162108, Building Permit - Residential

Address: 1713 SW NAPA VALLEY DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

**Erosion Control** Dale Carter Failed Friday, August 04, 2017

Corrective Action Required

1 Misc Remove soil and debris, and re-establish vegetation on adjacent

lot.

Occupancy Inspection - Dale Carter Codes Residential

Failed

Friday, August 04, 2017

Corrective Action Required

1 Misc

- 1. Remove soil and debris, and re-establish vegetation on adjacent lot.
- 2. Obtain approval of sanitary sewer connection (involving Public Works)
- 3. Final grade at front of house appears to have sunken; creating a low area that will collect water, and undermining the water meter cylindar, which will need reset.
- 4. Obtain sprinkler system permit.
- 5. Secure sprinkler line, near where it connects with water main in basement.
- 6. AC unit shall be protected by a 30amp-max breaker.
- 7. Secure / Adjust electric receptacle yokes throughout.
- 8. Need Lock-out/Tag-out brackets in breaker panel for oven, microwave, and vent-hood circuits.
- 9. Electric receptacle at the west wall of the garage needs GFI protection.
- 10. Rear door security screws.

## **Comments:**