

**PLANNING AND CODES ADMINISTRATION DEPARTMENT**  
**220 SE GREEN STREET**  
**LEE'S SUMMIT, MO 64063**  
**(816) 969-1200 FAX (816) 969-1201**

## Inspection Summary

---

Permit #:PRCOM20161756, Building Permit - Commercial  
Address: 795 NW DONOVAN RD, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	John Borns	Partial	Thursday, August 17, 2017

Partial Correction  
1        Misc

RATED ASSEMBLY AT STAIRWELLS:  
OK TO COVER 5/8" TYPE X MOLD TOUGH GWB AT

NORTH STAIRWELL WALLS: 2ND LAYER AT 1ST LEVEL WELL FACE + 1ST LAYER PRE-ROCK AT JOIST SPACE AT BACKSIDE; 1ST LAYER AT 2ND LEVEL WELL FACE; 2ND LAYER AT 2ND LEVEL WELL FACE + PRE-ROCK AT JOIST SPACE AT BACKSIDE; 1ST LAYER AT 3RD LEVEL WELL FACE; PRE-ROCK AT JOIST SPACE AT BACKSIDE AT 1ST, 2ND & 3RD FLOORS; 1ST LAYER AT 4TH FLOOR; 2ND LAYER AT 3RD & 4TH FLOORS; 1ST LAYER AT WALLS & CEILING ABOVE 4TH FLOOR; 2ND LAYER AT WALLS & CEILING ABOVE 4TH FLOOR; 3RD LAYER + RC CHANNEL AT LOW AND HIGH CEILINGS ABOVE 4TH FLOOR; [4TH LAYER AT LOW AND HIGH CEILINGS ABOVE 4TH FLOOR;

SOUTH STAIRWELL WALLS: 2ND LAYER AT 1ST LEVEL WELL FACE + 1ST LAYER PRE-ROCK AT JOIST SPACE AT BACKSIDE; 1ST LAYER AT 2ND LEVEL WELL FACE; 2ND LAYER AT 2ND LEVEL WELL FACE + PRE-ROCK AT JOIST SPACE AT BACKSIDE; 1ST LAYER AT 3RD LEVEL WELL FACE + PRE-ROCK AT JOIST SPACE AT BACKSIDE; 1ST LAYER AT 4TH FLOOR; 2ND LAYER AT 3RD & 4TH FLOORS; 1ST LAYER AT WALLS & CEILING ABOVE 4TH FLOOR; 2ND LAYER AT WALLS & CEILING ABOVE 4TH FLOOR; 3RD LAYER + RC CHANNEL AT LOW AND HIGH CEILINGS ABOVE 4TH FLOOR; 4TH LAYER AT LOW AND HIGH CEILINGS ABOVE 4TH FLOOR;

Partial Correction  
2        Misc

OK TO COVER WHEN READY RATED ASSEMBLY AT ELEVATOR SHAFT:

		1ST & 2ND LAYERS PERIMETER PRE-ROCK AT JOIST SPACE AT 1ST, 2ND, AND 3RD FLOORS;
		5/8" TYPE X GWB AT WELL FACE: 2ND LAYER AT 4TH, 3RD, 2ND, 1ST FLOORS
		SHAFT LID: 1ST LAYER; 2ND LAYER; 3RD LAYER;
Partial Correction		
3	Misc	OK TO COVER AT RATED CORRIDOR WALLS: 1ST FLOOR: 1ST LAYER 5/8" TYPE X GWB;
Partial Correction		
4	Misc	OK TO TAPE, MUD, AND FIRE-STOP GWB WALLS AT CLOSET AND MECH CLOSET AT TOP OF BOTH STAIRWELLS AT 4TH FLOOR
Partial Correction		
5	Misc	<b>OK TO COVER WHEN READY 1ST LAYER 5/8" TYPE X GWB AT 4TH FLOOR CEILINGS AND BACKSIDE OF STAIRWELLS AND ELEVATOR SHAFT;</b>

**All Rough Inspection - Commercial**

John Borns

Partial

Thursday, August 17, 2017

Partial Correction		
1	Misc	OK TO COVER WALL AND CEILING FRAMING + SYSTEMS FOR BE CONCEALED AT: BOTH STAIR TOWERS AT & ABOVE 4TH FLOOR; ALL SPACES AT 4TH FLOOR; ALL SPACES AT 3RD FLOOR INCLUDING STAIRWELLS, BALCONIES, AND CORRIDOR; <b>ALL SPACES AT 2ND FLOOR;</b>
		ACOUSTICAL FURRING CHANNELS FOUND TO BE INSTALLED AT 4TH FLOOR CORRIDOR.
Partial Correction		
2	Misc	<b>ABOVE-CEILING SPACE OK TO COVER WITH GWB AT SOUTH &amp; NORTH GARAGES TO ALLOW FUR-DOWN TO BE BUILT TO ENCLOSE ELECTRICAL SERVICE FEEDER CABLES</b>

**Comments:**